


Attachment #5



UPS Ground



1Z 404 364 03 1028 753 7

TRACKING NUMBER

10/97 W

CUSTOM PRODUCTS

C O R P O R A T I O N

2988 Bishop Rd
Wickliffe, OH 44092

701 Beta Drive

Cleveland, Ohio

44143

Dimas Amaro

333 Cohannet St.

Taunton, MA 02780-4102

DIMAS AMARO
333 COHANNET ST
TAUNTON MA 02780-4102



Delivery Co

SIGNATURE
REQUIRE

Label 228C August 1997

**HOW TO USE:
COMO USAR:**

1. COMPLETE ADDRESS LABEL AREA

Type or print required return address and addressee information in customer block (white area) or on label (if provided).

ESCRIBA LA DIRECCION EN EL AREA INDICADA

Escriba en letras de imprenta la dirección del remitente y la del destinatario en el cuadro blanco o en la etiqueta, si le fue provista.

2. PAYMENT METHOD

Affix postage or meter strip to area indicated upper right hand corner.

FORMA DE PAGO

Añadiera sello/franqueo por máquina al área indicada en la esquina superior derecha.

EVIDENCE # 4B PACKAGE #4

AT&T BROADBAND
CONVERTER TEST FORM

Date	3/09/01	Corp. #	<u>I-COMS</u>
Account #	43747-04	Converter #	004101587
Name:	Joe Amaro / Dimas Amaro	Converter Type:	<u>Global 2600</u>
Address:	333 Cohannet Street	Received From:	<u>Received from UPS on</u> <u>3/09/01</u>
City:	Taunton	State/Zip	<u>Ma. 02780</u>
SSN#:		Generated From:	

All Pay Channels YES All PPV Movies YES

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing
I Outside Screws Missing
R Converter Damaged
A Marks Around Outside Screw
T Wires Cut
E Tampered Codes

INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open
U ADP Module Cover Missing
N Scratches/Marks on Key Chips
I Jumper Wires Still In Place
T Scratches/Marks on Legs of Key Chips
 Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT